

Appendix F

Event/Action Plan for Noise Exceedance



Event and Action Plan for Construction Noise Monitoring

Event	Action							
	ET		IEC		ER		C	ontractor
Action Level	1. 2. 3. 4.	the source and cause of the complaint/ exceedance(s) Notify IEC, ER, and Contractor and report the results of Investigation to the Contractor, ER and the IEC	1. 2. 3.	Review the analyzed results submitted by the ET Review the proposed remedial measures by the Contractor and advise the ER accordingly Supervise the implementation of remedial measures	1. 2. 3.	Confirm receipt of Notification of Exceedance in writing Require Contractor to propose remedial measures for the analysed noise problem Ensure remedial measures are properly implemented	2.	Submit noise mitigation proposals, If required, to the IEC and ER Implement noise mitigation proposals.
imit Level		 Notify IEC, ER, EPD and Contractor Identify the source(s) of impact by reviewing all the relevant monitoring data and the corresponding construction activities. Exceedances should also be confirmed by immediate verification in the field as far as practical. Repeat measurement to confirm findings Increase monitoring frequency Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemente inform IEC, ER and EPD the cause & actions taken for the exceedances Assess effectiveness of Contractor's remedial actions and keep IEC, EPD ER informed of the results If exceedance stops, cease additional monitoring. 	ed.	 Discuss amongst ER, ET, and Contractor on the potential remedial actions Review Contractor's remedial actions to assure their effectiveness and advise the ER &ET accordingly Supervise the implementation of the remedial measures 	2. 3. 4. 5.	Confirm receipt of notification of exceedance in writing Notify Contractor Require Contractor to propose remedial measures for the analyzed noise problem Ensure remedial measures are properly implemented If exceedance continuous, consider what portion of the work is responsible and instruct the Contractor to stop that portion of work until the exceedance is aborted	2. 3. 4.	Take immediate action to avoid further exceedance Identify practicable measures to minimize the noise impact. Submit proposals for remedial actions to ER within three working days of notification Implement the agreed proposals Resubmit proposal if problem still not under control Stop the relevant portion of works as determined by the ER until the exceedance is abated