

Appendix E

Complaint Log

Statistical Summary of Environmental Complaints

Reporting Period	Environmental Complaint Statistics		
	Frequency	Cumulative	Complaint Nature
1 August 2023 – 31 October 2023	1	4	Air

Statistical Summary of Environmental Summons

Reporting Period	Environmental Summons Statistics		
	Frequency	Cumulative	Details
1 August 2023 – 31 October 2023	0	0	N/A

Statistical Summary of Environmental Prosecution

Reporting Period	Environmental Prosecution Statistics		
	Frequency	Cumulative	Details
1 August 2023 – 31 October 2023	0	0	N/A

Interim Report on Environmental Complaint

Project Title	Proposed Desalination Plant in TKO Area 137 for Contract 13/WSD/16 Mainlaying in Tseung Kwan O
Source of Complaint	Email from EPD to WSD dated on 21 September 2023
Location of Incident	Construction Site between Po Hong Road and Ling Hong Road
Complaint Code	13/WSD/16_C004
Complaint description	EPD has received a complaint lodged by a member of public regarding the emission of dark smoke from a WSD construction site between Po Hong Road and Ling Hong Road on 21 September 2023.
Investigation finding	<p>Our Environmental Team under WSD Contract No. 13/WSD/16 received the complaint case on 21 September 2023 and carried out the complaint investigation on 22 September 2023.</p> <p>Site investigation at the concerned area (Pit Y) has been carried out by ET on 22 September 2023. An excavator, suspected of being related to the complaint, was found in Pit Y. The contractor was requested to turn on the excavator so as to observe if there is any dark smoke emission. No dark smoke was observed while the excavator was in operation (the photo records for investigation shown in Appendix B1).</p> <p>After receiving the complaint, contractor and sub-contractor arranged a maintenance work for the excavator on 25 September 2023 (the photo records for maintenance work shown in Appendix B2) and moved the excavator to the workshop for further repairs on 28 September 2023 (the photo records for maintenance work shown in Appendix B3).</p> <p>Contractor provided the fuel purchase record and the diesel testing result, which shows the diesel used is Euro 5 diesel in Appendix C.</p>
Actions taken / to be taken	<p>The contractor has been reminded to check and maintain the machineries regularly to prevent any potential pollution and stop using the machineries if the condition could not be improved.</p> <p>Moreover, ET will perform spot checking on the concerned area the implementation status of mitigation measures. Contractor is reminded to comply with all regulations and requirement stipulated in the EM&A Manual.</p>

STATUS OF COMPLAINANT: *~~Follow-up~~/Closed

Prepared by: Alex Leung

Certified by: Jacky Leung

Designation: Environmental Team Member

Designation: Environmental Team Leader

Signature:




Signature:



Date: 6 October 2023

Date: 6 October 2023

Appendix A – Site Layout of Concerned Area



Appendix B1 – Photo Records from investigation

No dark smoke was emitted during the excavator operation on 22 September 2023.




NRMM label for the suspected excavator and other machinery being used on-site.



Appendix B2 – Photo Records of Maintenance Work

Maintenance was carried out on 25 September 2023



Appendix B3 – Photo Records of Maintenance Work

Removal work of excavator on 28 September 2023



Appendix C –Fuel Purchase Record and Latest Diesel Test Result

抹燭火泵油板
油油水油渣

經銷

輝捷國際有限公司

九龍觀塘海濱道133號萬兆豐中心17樓L室
電話：2686 1261 傳真：2686 1290

No. 472749

商號 望堯
地址 第湖仔

發票/送貨單 日期 4-8-2023

號No.碼	貨 Description 名	數 Quantity 量	單 Price 價	全 Amount 額
	EVO	25.7L		

收款時另發正式收據為憑，貨到驗明，收到作實。

合計 TOTAL \$

收貨人 Received By: [Signature]

交貨數量均以公升計算
請照單收貨如有錯誤或損破當面更正
貨到驗明簽署作實一經簽收不退不換
特此聲明

抹燭火泵油
板
油油水油渣

經銷

輝捷國際有限公司

九龍觀塘海濱道133號萬兆豐中心17樓L室
電話：2686 1261 傳真：2686 1290

No. 472775

商號 堅勇
地址 帝湖仔

發票/送貨單 日期 9-9-2023

號No.碼	貨 Description 名	數 Quantity 量	單 Price 價	金 Amount 額
	EVD	489L		

收款時另發正式收據為憑，貨到驗明，收到作實。

合計
TOTAL \$

收貨人
Received By: [Signature]

交貨數量均以公升計算
請照單收貨如有錯誤或損破當面更正
貨到驗明簽署作實一經簽收不退不換
特此聲明

抹燭火泵油
板
油油水油渣

經銷

輝捷國際有限公司

九龍觀塘海濱道133號萬兆豐中心17樓L室
電話：2686 1261 傳真：2686 1290

No. 472856

商號 聖堯
地址 萬湖仔

發票/送貨單 日期 15-9-2023

號No.碼	貨 Description 名	數 Quantity 量	單 Price 價	全 Amount 額
	EVO	275L		

收款時另發正式收據為憑，貨到驗明，收到作實。

合計
TOTAL \$

收貨人
Received By: [Signature]

交貨數量均以公升計算
請照單收貨如有錯誤或損破當面更正
貨到驗明簽署作實一經簽收不退不換
特此聲明

抹偶火泵油
板
油油水油渣

經銷

輝捷國際有限公司

九龍觀塘海濱道133號萬兆豐中心17樓L室
電話: 2686 1261 傳真: 2686 1290

No. 480169

商號 翠苑
地址 第101仔

發票/送貨單 日期 26-9-2023

號No. 碼	貨 Description 名	數 Quantity 量	單 Price 價	金 Amount 額
	E/D	398L		

收款時另發正式收據為憑，貨到驗明，收到作實。

交貨數量均以公升計算
請照單收貨如有錯誤或損破當面更正
貨到驗明簽署作實一經簽收不退不換
特此聲明

收貨人
Received By: [Signature]

合計
TOTAL \$

抹僞火泵油
板
油油水油渣

▲經銷▼

輝捷國際有限公司

九龍觀塘海濱道133號萬兆豐中心17樓L室
電話：2686 1261 傳真：2686 1290

No. 480201

商號 梁 葵
地址 葵 湖 仔

發票/送貨單 日期 29-9-2023

號No.碼	貨 Description 名	數 Quantity 量	單 Price 價	金 Amount 額
	EVD	148L		

收款時另發正式收據為憑，貨到驗明，收到作實。
交貨數量均以公升計算
請照單收貨如有錯誤或損破當面更正
貨到驗明簽署作實一經簽收不退不換
特此聲明

合 計
TOTAL \$

收 貨 人
Received By: [Signature]

GLORY VICTORY
輝捷國際有限公司

致: 巽堯建築有限公司

謹通知貴司, 我司交付之EVD為超低硫柴油, 符合現時香港環保法例,
並附上Specification給貴司參考.



Office L, 17/F, MG Tower, No.133 Hoi Bun Rd, Kwun Tong, Kln, Hong Kong 九龍觀塘海濱道133號萬兆豐中心17樓L室
Tel 電話: 2686 1261 Fax 傳真: 2686 1290 E-Mail 電郵: info@gloryvictory.com
郵寄地址: 沙田中央郵箱1830號 P.O.Box 1830, Shatin Central Post Office



中石化(香港)石油有限公司
SINOPEC (HONG KONG) PETROLEUM CO., LTD.

PRODUCT SPECIFICATION

EURO V DIESEL

<u>TEST ITEM</u>	<u>TEST METHOD</u>		<u>SPECIFICATION</u>
Appearance @25°C	外觀	目測	Clear & bright
Color	色度	ASTM D1500	2.0 max. (Cap311L not required)
Cetane Number	十六烷值	ASTM D613	51 min.
Cetane Index	十六烷指數	ASTM D4737	46 min
Density at 15°C, g/cm3	密度	ASTM D4052	0.820-0.845
Polycyclic Aromatic Hydrocarbon, wt%	多環芳香烴化合物	ASTM D6591	11 max.
Sulfur, mg/Kg	含硫量	ASTM D5453	10 max.
Flash Point °C	閃點	ASTM D93	>60°C
Carbon Residue (10% distillation), wt%	殘炭	ASTM D4530	0.30 max.
Ash, wt%	灰分	ASTM D482	0.01 max.
Water content, mg/Kg	水分	ASTM D6304	200 max.
Total contamination, mg/Kg	總污染物	ASTM D5452	24 max.
Copper Strip Corrosion (3 Hours at 50°C)	銅片腐蝕	ASTM D130	Class 1
Oxidation Stability, g/m3	氧化穩定性	ASTM D2274	25 max.
Lubricity corrected wear scar diameter (WSD1.4) at 60°C, µm	校正磨痕直徑	ASTM D6079	460 max.
Viscosity Kin. at 40°C, cst	黏度	ASTM D445	2.0-4.5
Distillation	蒸餾	ASTM D86	
-Recovery at 250°C, vol%			65 max.
-Recovery at 350°C, vol%			85 min.
-95% Recovered, °C			360 max.



Qualitech Testing & Consultancy Limited

匯駿檢測及顧問有限公司

Flat E & F, 9/F, Block B, Universal Industrial Centre, 19-25 Shan Mei Street, Sha Tin, Hong Kong.


新界火炭山尾街19-25號宇街工業中心B座9樓E&F室

Tel : (852) 2185-0900 Fax : (852) 2687-6752 Website : www.qtc-hk.com E-mail : qtc@qtc-hk.com

TEST REPORT

TOTAL SULFUR CONTENT OF DIESEL FUEL

[ASTM D2622-16, Excluding Cl. 5.2, Cl. 5.3 and Cl. 8.1]

Report No. : 2308323-1	Rev.: 0	Amd.: 0	Issued date : 9 August, 2023	Page 1 of 1	Page(s)
Date of received : 7 August, 2023			Date of test : 8 August, 2023		
Customer information : (provided by customer)					
Customer's name : Penta-Ocean - Concentric Joint Venture					
Customer's address : Unit 601, K. Wah Centre, 191 Java Road, North Point, Hong Kong					
Contract no. : 13/WSD/16			Work order no. : -		
Project : Mainlaying in Tseung Kwan O					
Sample description : B5 Diesel					
Location : Pit Y					
Date of sampled : 31 July, 2023			Sample I.D. no. : A-20230731		
Test result :-					
Test Item				Results	
Total sulfur content				mg/kg	6.8
				%	0.00068
Remark:-					
1. Test location : QTC - Flat E, 6/F, Block B, Universal Industrial Centre.					
2. Test result relates to the specimen tested only.					
Approved Signatory :				 Lam Siu Ping	
End of Report					

CHIMASTMD2622STR20210920Amd3



Qualitech Testing & Consultancy Limited

匯駿檢測及顧問有限公司

Flat E & F, 9/F, Block B, Universal Industrial Centre, 19-25 Shan Mei Street, Sha Tin, Hong Kong.


新界火炭山尾街19-25號宇街工業中心B座9樓E&F室

Tel : (852) 2185-0900 Fax : (852) 2687-6752 Website : www.qtc-hk.com E-mail : qtc@qtc-hk.com

TEST REPORT

TOTAL SULFUR CONTENT OF DIESEL FUEL

[ASTM D2622-16, Excluding Cl. 5.2, Cl. 5.3 and Cl. 8.1]

Report No. : 2308323-2	Rev.: 0	Amd.: 0	Issued date : 9 August, 2023	Page 1 of 1	Page(s)
Date of received : 7 August, 2023			Date of test : 8 August, 2023		
Customer information : (provided by customer)					
Customer's name : Penta-Ocean - Concentric Joint Venture					
Customer's address : Unit 601, K. Wah Centre, 191 Java Road, North Point, Hong Kong					
Contract no. : 13/WSD/16			Work order no. : -		
Project : Mainlaying in Tseung Kwan O					
Sample description : B5 Diesel					
Location : Pit Y					
Date of sampled : 31 July, 2023			Sample I.D. no. : B-20230731		
Test result :-					
Test Item				Results	
Total sulfur content				mg/kg	7.3
				%	0.00073
Remark:-					
1. Test location : QTC - Flat E, 6/F, Block B, Universal Industrial Centre.					
2. Test result relates to the specimen tested only.					
Approved Signatory :				 Lam Siu Ping	
End of Report					

CHIMASTMD2622STR20210920Amd3